

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherwon USA Inc	API Number 30-025-3808 ✓
Property Name Vacuum Colorado West Unit	Well No. 67 ✓

Surface Location

UL - Lot 6	Section 36	Township 17S	Range 34E	Feet from 1435	N/S Line S N	Feet From 1408	E/W Line E	County LEA ✓
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES	YES (NO)	SHUT-IN YES	NO (NO)	INJECTOR YES (NO)	SWD	OIL	PRODUCER GAS	DATE 5/7/15
------------------	-----------------	----------------	----------------	-----------------------------	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	500
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 — WTR X GAS —
Steady Flow	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Surges	Y/N	Y/N	Y/N	Y/N	Injected for
Down to nothing	Y/N	Y/N	Y/N	Y/N	Water flood if
Gas or Oil	Y/N	Y/N	Y/N	Y/N	applies
Water	Y/N	Y/N	Y/N	Y/N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B& 7/14/2015

Signature: Tanner Dutton	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TANNER@cherwon.com	
Date: 5/7/15	Phone:
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015