

HOBBS OGD
JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chercon USA Inc	API Number 30-025-31841
Property Name Vacuum Colonia West Unit	Well No. 94

Surface Location									
UL - Lot 5	Section 36	Township 17S	Range 34E		Feet from 1575	N/S Line S	Feet From 2591	E/W Line E	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 5/1/15	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	6	2/A	2/A	6	6
Flow Characteristics					OK
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
BS 7/14/2015

Signature: Tanner Deltan	OIL CONSERVATION DIVISION
Printed name: Tanner Deltan	Entered into RBDMS
Title: BSA	Re-test
E-mail Address: TDR @ chercon.com	
Date: 5/1/15	
Witness: George Dow	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015