

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chercon USA Inc	API Number 30-025-31842
Property Name Vacuum Colonia West Unit	Well No. 81

7. Surface Location

U/L - Lot 14 J	Section 36	Township 17S	Range 34E	Feet from 2521	N/S Line S	Feet From 1503	E/W Line E	County LEA
--------------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 5/1/15
--	--	--	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	n/a	n/a	ϕ	ϕ
Flow Characteristics					
Pull	Y / N ☒	Y / N	Y / N	Y / N ☒	CO2 ☐
Steady Flow	Y / N ☒	Y / N	Y / N	Y / N ☒	WTR ☒
Surges	Y / N ☒	Y / N	Y / N	Y / N ☒	GAS ☐
Down to nothing	Y / N ☒	Y / N	Y / N	Y / N ☒	Type of Fluid
Gas or Oil	Y / N ☒	Y / N	Y / N	Y / N ☒	Injected for
Water	Y / N ☒	Y / N	Y / N	Y / N ☒	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/4/2015

Signature: Tanner	Chercon	OIL CONSERVATION DIVISION
Printed name: Tanner Deltac		Entered into RBDMS
Title: PSA		Re-test
E-mail Address: TDR @ chercon.com		
Date: 5/1/15	Phone:	
Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015

h