

JUL 10 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherren USA INC	API Number 30-025-31843
Property Name Vacuum Colerita West Unit	Well No. 95

2. Surface Location

UL - Lot 5	Section 36	Township 17S	Range 34E	Feet from 1534	N/S Line S	Feet From 1521	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL. YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR ☒ SWD ☒	OIL ☒ GAS ☒	DATE 5/1/15
--	---	---	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1500
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☒
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Tanner Detman	OIL CONSERVATION DIVISION
Printed name: Tanner Detman	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T242@cherren.com	
Date: 5/1/15	Phone:
Witness: George Brown	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015