

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherwon USA Inc						API Number 30-025-31871			
Property Name Vacuum Colorado West Unit						Well No. 63			
2 Surface Location									
1/4 - Lot H	Section 35	Township 17S	Range 34E	Feet from 1340	N/S Line N	Feet from 1090	E/W Line E	County LEA	
Well Status									
YES	TEST WELL NO	YES	SHUT-IN NO	NO	INJECTOR NO	SWD	OIL	PRODUCER NO	GAS NO
									DATE 5/1/15

OBSERVED DATA

	(A)Surface	(B)Internt(1)	(C)Internt(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	1100
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Tanner DeHaan	chevron	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	BSA	Entered into RBDMS
Title: BSA		Re-test
E-mail Address: TANNER@chevron.com		
Date: 5/1/15	Phone:	
	Witness: George Owen	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015