

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherxon USA Inc	API Number 30-025-31879
Property Name Vacuum Calorita West Unit	Well No. 124

1. Surface Location

U/L - Lot B	Section 6	Township 18S	Range 35E	Feet from 1020	N/S Line N	Feet From 1514	E/W Line E	County LEA
-----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

T&D WELL ☒ YES	☒ NO	SHUT-IN ☒ YES	☒ NO	INJECTOR ☒ YES	☒ NO	SWD ☒ YES	☒ NO	OIL ☒ YES	☒ NO	PRODUCER ☒ YES	☒ NO	GAS ☒ YES	☒ NO	DATE 5/7/15
--	-------------------------------------	---	-------------------------------------	--	-------------------------------------	---	-------------------------------------	---	-------------------------------------	--	-------------------------------------	---	-------------------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	2 1/2	2 1/2	0	1400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/14/2015

Signature: Tanner Dutton	Cherxon	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton		Entered into RBDMS
Title: FSA		Re-test
E-mail Address: T2Y1@cherxon.com		
Date: 5/7/15	Phone:	
Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 15 2015