

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-32004 ✓
Property Name VGSAU	Well No. 212 ✓

Surface Location

BL - Lot 0	Section 1	Township 18S	Range 34E	Feet from W20	N/S Line S	Feet from 11250	E/W Line E	County Lea ✓
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	---------------------------	----------------------	------------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ INJ	SWD SWD	PRODUCER ☒ OIL	GAS GAS	DATE 5-28-15
------------------	-------------------------------------	----------------	-------------------------------------	------------	------------	--	------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			90	110
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Type of Fluid Injected for
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Water shed if applies
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2014

Signature 	OIL CONSERVATION DIVISION
Printed name: Austin Pogue	Entered into RBDMS
Title: PSA	Re-test
Email Address: etym@chevron.com	
Date: 5-28-15	Phone: 575-513-0363

RECEIVED JUN 19 2015

JUL 15 2015