

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-32028
Property Name VCSA	Well No. 128

Surface Location

Section 1	Section 41	Township 18S	Range 34E	Feet from 1900	NS Line 1/5	Feet from 1220	EW Line E	County Lea
---------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------	--------------------------	---------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL	GAS GAS	DATE 5-28-15
------------------	-----------	----------------	-----------	------------	------------	------------------------	------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			40	360
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected Ice
Water	Y / N	Y / N	Y / N	Y / N	Water level if applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 6/30/2015 -

Signature: A. Pagan	OIL CONSERVATION DIVISION
Printed name: Austin Pagan	Entered into RWDMS
Title: FSA	Re-test
Email Address: etyp@chevron.com	
Date: 5-28-15	Phone: 575-513-0363

JUL 15 2015