

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	API Number 30-025-33429
Property Name VGWU	Well No. 89

Surface Location

BL. Lat I	Section 36	Township T17S	Range R34E	Feet from 2000	NS Line S	Feet from 1070	EW Line E	County Lea
---------------------	----------------------	-------------------------	----------------------	--------------------------	---------------------	--------------------------	---------------------	----------------------

Well Status



TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 5/20/15
------------------	----	----------------	----	-----	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	ϕ	N/A	N/A	55	110
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterhead if applies

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: ALEX ORMSBY	Entered into RBDMS
Title: FS	Re-test
E-mail Address: EOXF@CHEVRON.COM	
Date: 5/20/15	Phone: 575 513 5521
	

JUL 15 2015