

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chewon	API Number 30-025-38627 ✓
Property Name VGSAU	Well No. 327 ✓

Surface Location

ML - Lot K	Section 201	Township 18S	Range 34E	Feet from 1945	N/S Line S	Feet from 2585	E/W Line W	County LEA ✓
----------------------	-----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status


TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR SWD	PRODUCER OIL	GAS	DATE 5-27-15
------------------	----------------	-----------	-----------------	------------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	NA	50	250
Flow Characteristics					
Puff	Y / X	Y / X	Y / N	Y / X	CO2 ___
Steady Flow	Y / X	Y / X	Y / N	Y / X	WTR ___
Surges	Y / X	Y / X	Y / N	Y / X	GAS ___
Down to nothing	Y / X	Y / X	Y / N	Y / X	Type of fluid
Gas or Oil	Y / X	Y / X	Y / N	Y / X	Injected for
Water	Y / X	Y / X	Y / N	Y / X	Watered off if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 6/30/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Austin Payne	Entered into RIDMS
Title: FSA	Re-test
Email Address: etym@chevron.com	
Date: 5-27-15	Phone: 575-513-0343

JUL 15 2015

