

JUL 10 2015

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherwon USA Inc	API Number 30-025-31700 ✓
Property Name Vacuam Colorado West Unit	Well No. 39 ✓

2. Surface Location

DL - Lot M	Section 25	Township 17S	Range 34E	Feet from 1144	N/S Line S	Feet From 1055	E/W Line W	County LEA -
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 5/7/15
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BR 7/14/2015

Signature: Tanner Dutton	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TDR @ cherwon.com	
Date: 5/7/15	Phone:
Witness: Joey Brown	

JUL 16 2015

INSTRUCTIONS ON BACK OF THIS FORM

4