

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cherwon USA Inc	API Number 30-025-31814
Property Name Vacuum Colonia West Unit	Well No. 31

7. Surface Location									
Oil - Lot 1	Section 25	Township 17S	Range 34E	Feet from 2520	N/S Line S	Feet From 153	E/W Line E	County LEA	

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 5/7/15
-------------------------	----	-----------------------	----	------------------------	-----	-----	------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	ϕ
Flow Characteristics					
Pull	ϕ / N	Y / N	Y / N	ϕ / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	ϕ / N	Y / N	Y / N	ϕ / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BB 7/14/2015

Signature: Tanner Dutton	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T2YR@cherwon.com	
Date: 5/7/15	
Phone:	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 16 2015