

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherwon USA Inc	API Number 30-025-31834 ✓
Property Name Vacuam Colonia West Unit	Well No. 5 ✓

Surface Location

UL - Lot N	Section 24	Township 17S	Range 34E	Feet from 1209	N/S Line S	Feet From 2582	F/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TAB WELL YES	NO ✓	SHUT-IN YES	NO ✓	INJECTOR IN ✓	SWD	OIL	PRODUCER GAS	DATE 5/7/15
-----------------	-------------	----------------	-------------	-------------------------	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	φ	21A	21A	φ	1200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Tanner Cherwon	OIL CONSERVATION DIVISION
Printed name: Tanner Cherwon	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TTC@cherwon.com	
Date: 5/7/15	
Phone:	
Witness: Joy Down	

JUL 16 2015

INSTRUCTIONS ON BACK OF THIS FORM