

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 19 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron	API Number 30-025-38788 ✓
Property Name Vacuum Corralburg San Andres Unit	Well No. 241 ✓

2. Surface Location

UT - Twp A	Section 1	Township 18S	Range 34E	Feet from 170	N/S Line N	Feet from 710	E/W Line W	County LEA ✓
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	------------------------

Well Status

YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	(INT)	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 5-21-2015
-----	--------------------------	-----	------------------------	--------------	----------	-----	-----	----------	-----	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	50	1650
Flow Characteristics					
Pull	Y / (N)	Y / N	Y / N	(N) / N	CO2 X
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR X
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	(N) / N	Y / N	Y / N	(N) / N	Type of Fluid
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	Injected for
Water	Y / (N)	Y / N	Y / N	Y / (N)	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D - Gas bled to zero in 5 minutes

BS 6/30/2015

Signature: T. De Chevron	OIL CONSERVATION DIVISION
Printed name: Tanner DeChen	Entered into RBDMS
Title: FS	Re-test
E-mail Address: T2YK@chevron.com	
Date:	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

JUL 16 2015