

JUN 30 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron						API Number 30-025-26281 ✓			
Property Name Vacuum Grayburg San Andres Unit						Well No. 59 ✓			
Surface Location									
BL - Lot E	Section 2	Township 18S	Range 34E		Feet from 2500	N/S Line N	Feet from 40	FAW Line W	County Lea

Well Status



YES	TAID WELL NO	YES	SHUT-IN NO	INJECTOR NO	SWD	OIL	PRODUCER	GAS	DATE 4/23/15
-----	------------------------	-----	----------------------	-----------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ	φ	2/15	φ	1800
Flow Characteristics					
Pull	Y / N	N / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	N / N	N / N	Y / N	N / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: 	OIL CONSERVATION DIVISION	
Printed name: Tammie Chevron	Entered into RBDMS	
Title: FSA	Re-test	
E-mail Address: Tammie Chevron.com		
Date: 4/23/15	Phone: 505-310-4449	
Witness: 		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015