

JUN 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron						API Number 30-025-26282			
Property Name Vacuum Grayburg San Andres Unit						Well No. 600			
2. Surface Location									
U/L - Lot D	Section 2	Township 18S	Range 34E	Feet from 1320		N/S Line WN	Feet from 1320	E/W Line N	County LEA
Well Status									
YES	TAB WELL NO	YES	SHUT-IN NO	INJ NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 4/23/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1850
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: Tanner	OIL CONSERVATION DIVISION	
Printed name: Tanner Peterson	Entered into RBDMS	
Title: FSA	Re-test	
E-mail Address: Tanner@chevron.com		
Date: 4/23/15	Phone: 575-390-9449	
Witness: George Dow		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015