

JUN 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name Chevron						API Number 30-025-30847 ✓			
Property Name Vacuum Grayburg San Andres Unit						Well No. 149 ✓			
2. Surface Location ✓									
UL - Lot C	Section 1	Township 18S	Range 34E		Feet from 1330	N/S Line N	Feet From 1980	FWW Line W	County CEA
Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 4/23/15

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod. Casing	(E) Tubing
Pressure	ϕ	ϕ	2/1	ϕ	1800
Flow Characteristics					
Pull	ϕ / N	ϕ / N	Y / N	ϕ / N	CO ₂ X
Steady Flow	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	WTR X
Surges	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	GAS —
Down to nothing	ϕ / N	ϕ / N	Y / N	ϕ / N	Type of fluid
Gas or Oil	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	Injected for
Water	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2013 -

Signature:		OIL CONSERVATION DIVISION
Printed name:	T. J. D.	Entered into RBDMS
Title:	PSA	Re-test
E-mail Address:	TJ.D@chevron.com	
Date:	4/23/15	
Phone:	575-350-4444	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015