

JUN 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT



Operator Name Chevron						API Number 30-025-35561			
Property Name Vacuum Grayburg San Andres Unit						Well No. 135			
Surface Location									
W. - Lot 6	Section 1	Township 18S	Range 34E	Feet from 2535	N/S Line N	Feet from 1430	E/W Line E	County LEA	
Well Status									
TAPED WELL NO		SHIFT-IN NO		INJECTOR NO		PRODUCER NO		DATE 4/23/15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	ϕ
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS X
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: T. R. Patton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TRP@chevron.com	
Date: 4/23/15	Phone: 505-390-5449
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015