

JUN 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherren	API Number 30-025-40994 ✓
Property Name Vacuum Corayburg San Andres Unit	Well No. 247

Surface Location									
U.L. - Lot H	Section 2	Township 18S	Range 34E		Feet from 1800	N/S Line N	Feet From 145	E/W Line E	County LEA

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJECTOR NO	SWD	OIL	PRODUCER	GAS	DATE 4/23/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ	φ	2 1/4	φ	1800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 Y
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR Y
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: T. R. R.	OIL CONSERVATION DIVISION
Printed name: T. R. R.	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T. R. R. cherren.com	
Date: 4/23/15	Phone: 505 390 4449
Witness: J. R. R.	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015