

JUN 30 2015

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6101 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	*API Number 30-025-02231
Property Name CENTRAL VACUUM UNIT	Well No. 52

2. Surface Location

UL - Lot B	Section 36	Township 17S	Range 34E	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County LOA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR SWD	PRODUCER OIL	GAS	DATE 3-25-15
------------------	----------------	-----------	-----------------	-----------------	-----	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	260	550
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Water flood if applies
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PROD CASING HAD GAS - BLOW DOWN TO ZERO
STAYED ZERO 24 HRS LATER ?

BS 7/2/2015

Signature 	OIL CONSERVATION DIVISION
Printed name: JAMESON EVANS	Entered into RBDMS
Title: FIELD SPECIALIST A	Re-test
E-mail Address: LKKM @ CHEVRON.COM	
Date: 6-25-15	Phone: 575 704 2467
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015