

HOBBS OCD

JUN 30 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON					API Number 30252 4754				
Property Name CENTRAL VACUUM UNIT					Well No. 111				
7. Surface Location									
UL - Lot K	Section 6	Township 18S	Range 35E	Feet from 2310	N/S Line S	Feet From 1750	E/W Line W	County Lea	
Well Status									
TA'D WELL YES	☒ NO ☒ YES		SHUT-IN NO	INJ	INJECTOR SWD	☒ OIL ☐ GAS	DATE 3-25-15		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	50			50	30
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

WELL WAITING ON RIG = BAD PUMP

Bk 7/2/2015

Signature: Jameson Evans	OIL CONSERVATION DIVISION
Printed name: JAMESON EVANS	Entered into RBDMS
Title: FIELD SPECIALIST A	Re-test
E-mail Address: LKKM @ CHEVRON. COM	
Date: 3-25-15	Phone: 575 704 2467
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 21 2015