

JUN 30 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name chevron					API Number 30-025-24317				
Property Name Vacuum Grayburg San Andres Unit					Well No. 18				
Surface Location									
U. - Lat K	Section 1	Township 18S	Range 34E	Feet from 1330	N/S Line S	Feet from 1330	E/W Line W	County Lea	
Well Status									
YES	TAND WELL NO	YES	SHUT-IN NO	INJ NO	SWD	OIL	PRODUCER	GAS	DATE 4/23/15

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	ϕ	N/A	N/A	ϕ	1200
Flow Characteristics					
Pull	ϕ N	Y / N	Y / N	ϕ Y / N	CO2
Steady Flow	Y / ϕ	Y / N	Y / N	Y / ϕ	WTI 2
Surges	Y / ϕ	Y / N	Y / N	Y / ϕ	GAS
Down to nothing	ϕ N	Y / N	Y / N	ϕ Y / N	Type of Fluid
Gas or Oil	Y / ϕ	Y / N	Y / N	Y / ϕ	Injected for
Water	Y / ϕ	Y / N	Y / N	Y / ϕ	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: Tanner		OIL CONSERVATION DIVISION	
Printed name: Tanner Deaton		Entered into RBDMS	
Title: FSA		Re-test	
E-mail Address: Tanner@chevron.com			
Date: 4/23/15	Phone: 505 380 4445		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015