

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 30 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name chevron	API Number 30-025-24333
Property Name Vacuum Grayburg San Andres Unit	Well No. 5

2. Surface Location									
BL - Lot N	Section 1	Township 18S	Range 34E	Feet from 210	N/S Line S	Feet from 1420	E/W Line W	County LEA	

Well Status

TAB WELL YES	NO (C)	SHUT-IN YES	NO (C)	INJECTOR NO (C)	SWD	OIL	PRODUCER GAS	DATE 4/23/15
-----------------	---------------	----------------	---------------	---------------------------	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	ϕ	ϕ	2/4	ϕ	1700
Flow Characteristics					
Puff	Y/N (C)	Y/N (C)	Y/N	Y/N (C)	CO2 —
Steady Flow	Y/N (C)	Y/N (C)	Y/N	Y/N (C)	WTR X
Surges	Y/N (C)	Y/N (C)	Y/N	Y/N (C)	GAS —
Down to nothing	(C) /N	(C) /N	Y/N	(C) /N	Type of Fluid
Gas or Oil	Y/N (C)	Y/N (C)	Y/N	Y/N (C)	Injected for
Water	Y/N (C)	Y/N (C)	Y/N	Y/N (C)	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/21/2015

Signature: Tamara A. Haan	OIL CONSERVATION DIVISION
Printed name: Tamara A. Haan	Entered into RBDMS
Title: ISA	Re-test
E-mail Address: Tamara@chevron.com	
Date: 4/23/15	Phone: 505-310-9949
Witness: George Brown	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015