

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 30 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-24360 ✓
Property Name Vacuum Grayburg San Andres Unit	Well No. 20 ✓

Surface Location									
UL - Lot 5	Section 1	Township 18S	Range 34E	Feet from 1330	N/S Line S	Feet From 1330	E/W Line E	County LEA	



Well Status									
TAB WELL YES	NO ☒	YES	SHUT-IN NO ☒	YES	INJECTOR NO ☒	YES	PRODUCER NO ☒	YES	DATE 4/23/15

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	N/A	N/A	Ø	Ø
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Ø / N	CO2 ☒
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☒
Down to nothing	Ø / N	Y / N	Y / N	Ø / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name Tanner DeHaven	Entered into RBDMS
Title: ESA	Re-test
E-mail Address: TANNER.CHEVRON-LEA	
Date: 4/23/15	Phone: 575-390 4441
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015

