

JUN 30 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name chevron					API Number 30-025-24363				
Property Name Vacuum Grayburg San Andres Unit					Well No. 46				
2. Surface Location									
UL - Lot C	Section 2	Township 18S	Range 34E	Feet from 1310	N/S Line N	Feet from 1230 2530	F/W Line E W	County LEA	
Well Status									
TAND WELL YES		☒ NO		SHUT-IN YES		☒ NO		INJECTOR SWD	
								OIL PRODUCER GAS	
								DATE 4/23/15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	1850
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	☒ Y / N	CO2 ☒
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☒
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/2/15

Signature: Tanner	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaven	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T2X1 @ chevron.com	
Date: 4/23/15	Phone: 505-390 4449
Witness: George	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015