

JUL 09 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.	API Number 30-025-30622
Property Name East Corbin Delaware Unit	Well No. 1

Surface Location

UL - Lot M	Section 16	Township 18S	Range 33E	Feet from 548'	N/S Line South	Feet From 760'	E/W Line West	County Lea
---------------	---------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Active	PRODUCING injection	DATE 06/08/2015
-------------	-------------------	------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0		0	0	800
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

- (A) Opened valve, just a slight puff. Tested for 15 minutes.
(C) Opened valve, just a slight puff. Tested for 15 minutes.
(D) Opened valve, blew a gallon of water and skim of oil. Blew down to nothing in 2 minutes. Tested for 15 minutes. Well was not active during test.

Field information submitted by Candy Aguilar.

BS 7/14/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan_wagner@eoqresources.com	
Date:	Phone: 432-686-3689
	Witness:

JUL 22 2015