

JUL 09 2015

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

## BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.	API Number 30-025-30683
Property Name West Corbin Fed	Well No. 16

## 1. Surface Location

UL - Lot O	Section 7	Township 18S	Range 33E	Feet from 800'	N/S Line South	Feet from 1980'	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	--------------------	------------------	---------------

## Well Status

Well Status	SHUT-IN Active	PRODUCING SWD	DATE 06/09/2015
-------------	-------------------	------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0		0	0	1200
Flow Characteristics					
Puff	(Y) / N	Y / N	(Y) / N	(Y) / N	
Steady Flow	Y / (N)	Y / N	Y / (N)	Y / (N)	
Surges	Y / (N)	Y / N	Y / (N)	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / (N)	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / (N)	Y / (N)	
Water	Y / (N)	Y / N	Y / (N)	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

## Remarks:

- (A) Opened valve, just a slight puff. Tested for 15 minutes.  
(C) Opened valve, just a slight puff. Tested for 15 minutes.  
(D) Opened valve, just a slight puff. Tested for 15 minutes.  
Well was not active during pressure test.

Field information submitted by Candy Aguilar.

BS 7/14/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan.wagner@eogresources.com	
Date:	Phone: 432-686-3689
	Witness:

JUL 22 2015