

JUL 09 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.		API Number 30-025-30949
Property Name East Corbin Delaware Unit		Well No. 3

7. Surface Location

UL - Lot 0	Section 16	Township 18S	Range 33E	Feet from 660'	N/S Line South	Feet From 1980'	E/W Line East	County Lea
---------------	---------------	-----------------	--------------	-------------------	-------------------	--------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Active	PRODUCING injection	DATE 06/08/2015
-------------	-------------------	------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0			0	500
Flow Characteristics					
Puff	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	
Steady Flow	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	
Surges	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	
Down to nothing	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	
Gas or Oil	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	
Water	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Y <input type="checkbox"/> N	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR <input checked="" type="checkbox"/>	FRESH	SALTY	SULFUR	BLACK
---	-------	-------	--------	-------

Remarks:

- (A) Opened valve, just a puff. Tested for 15 minutes.
(D) Opened valve, blew out a gallon of water and a skim of oil.
Blew down to nothing in 1 minute. Tested for 15 minutes.
Well was not active during test.

Field information submitted by Candy Aguilar

Bl 7/14/2015

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Stan Wagner		Entered into RBDMS	
Title: Regulatory Analyst		Re-test	
E-mail Address: stan_wagner@eoqresources.com			
Date:	Phone: 432-686-3689		
Witness:			

JUL 22 2015