

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron USA, Inc.	API Number 30-025-31874
Property Name Vacuum Colonia West Unit	Well No. 106

Surface Location									
UL - Lot 0	Section 36	Township 17S	Range 34E		Feet from 3/6	N/S Line S	Feet from 2630	E/W Line E	County LEA

Well Status									
YES	NO	YES	NO	INJ	SWD	OIL	GAS	DATE 5/1/15	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	N/A	N/A	ϕ	650
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
BS 7/14/2015

Signature: Turner Detken	OIL CONSERVATION DIVISION
Printed name: Turner Detken	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TDetken@chevron.com	
Date:	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015