

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 10 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherxon USA, Inc.	API Number 30-025-31877 ✓
Property Name Vacuum Colonia West Unit	Well No. 122 ✓

Surface Location									
1/4 - 1/4	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
D	6	18S	35E		845	N	1061	W	LEA

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
		NO			NO	IN					5/7/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1550
Flow Characteristics					
Poll	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BL 7/14/2015

Signature: Tanner Cherxon	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T242@cherxon.com	
Date: 5/7/15	Phone:
Witness: [Signature]	

JUL 22 2015

INSTRUCTIONS ON BACK OF THIS FORM