

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	API Number 30-025-31884
Property Name Vacuum Glorieta West Unit	Well No. 107

Surface Location

UL - Lot P	Section 36	Township 17S	Range 34E	Feet from 183	N/S Line S	Feet from 931	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status




TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 5/1/15
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	φ	N/A	N/A	φ	1250
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: 	chevron	OIL CONSERVATION DIVISION
Printed name: Turner Deffen		Entered into RBDMS
Title: FSA		Re-test
E-mail Address: TURNER.chevron.com		
Date: 5/1/15	Phone: 	
	Witness: 	

JUL 22 2015

INSTRUCTIONS ON BACK OF THIS FORM

