

HOBBS OCD

JUL 13 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON Midcontinent	API Number 30-025-05412
Property Name LIVINGSTON Paddock Unit	Well No. 53 -

UL - Lot A	Section 6	Township 36E	Range 37E	Feet from 330	N/S Line N	Feet From 840	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

1. Surface Location

Well Status

PROD WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 6-24-15
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/28/2015

Signature: Wendy Menden	OIL CONSERVATION DIVISION
Printed name: Wendy Menden	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: wmbb@chevron.com	
Date: 6-24-15	Phone: 707 59 3254
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 30 2015