

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-03106
Property Name ABC REEF State AN	Well No. AN-6

Surface Location

Section 0	Block 7	Subblock 18S	Range 35E	Section 090	Subsection S	Foot Contour 2310	Flow Line E	Leak LEA
---------------------	-------------------	------------------------	---------------------	-----------------------	------------------------	-----------------------------	-----------------------	--------------------

Well Status


TEST AVELL YES ☒	SHUT-IN YES ☒	INJECTOR INJ ☒	SWD SWD ☒	PRODUCER GAS ☒	DATE 5/27/15
---	--	---	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm1	(C)Interm2	(D)Prod Csg	(E)Tubing
Pressure	45	45	45	45	70
Flow Characteristics					
Pull	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	WTR ☐
Surges	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Type of Fluid
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Injected for
Water	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Waterhead if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BL 7/29/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Ruben	Entered into RBDMS
Title: FSA	Re-test
Email Address: TECL@chevron.com	
Date: 5/27/15	Phone: 575-513-5526

JUL 31 2015

