

JUL 13 2015

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0730

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON Midcontinent		API Number 30-025-03826	
Property Name Crawford PADDLE UNIT		Well No. 59	
Surface Location			
UL - Lot 6	Section 1	Township 17S	Range 36E
Feet from 2080		N/S Line N	Feet From 1980
EAV Line E		County LEA	

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ INJ	SWD	OIL	PRODUCER	GAS	DATE 6-24-15
-----	------------------------	-----	----------------------	-------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	0	1800
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ✓
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water/Bleed if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/28/2015

Signature: Cheryl Mendoza		OIL CONSERVATION DIVISION	
Printed name: Cheryl Mendoza		Entered into RBIMS	
Title: Pumpet		Re-test	
E-mail Address: cmendoza@chevron.com			
Date: 6-24-15	Phone: 970 759 3254		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015