

JUL 13 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON Midcontinent	API Number 30-025-03831
Property Name LOUINGTON PADDock UNIT	Well No. 60 -

Surface Location									
UL - Lot F	Section 1	Township 17S	Range 36E	Feet from 1980	N/S Line N	Feet From 2310	E/W Line W	County LEA	

Well Status									
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ ☒	SWD ☐	OIL ☐	PRODUCER ☐	GAS ☐	DATE 6-25-15		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	0	1350
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/28/2015

Signature: Wich Mendez	OIL CONSERVATION DIVISION
Printed name: Wich Mendez	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: wmbb@chevron.com	
Date: 6-25-15	Phone: 970 789 3254
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015

[Handwritten signature]