

JUL 14 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06400
Property Name NEDU		Well No. 102 2

Surface Location

UL - Lot A	Section 4	Township 21S	Range 37E	Feet from 1582	N/S Line N	Feet From 990	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD	PRODUCER OIL ☐ GAS ☐	DATE 5-17-15
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	1000 $\emptyset$	$\emptyset$	$\emptyset$		1200
Flow Characteristics					
Puff	☒ Y / ☐ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	WTR ☒
Surges	Y / ☒ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	GAS ☐
Down to nothing	☒ Y / ☐ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	
Water	Y / ☒ N	Y / ☐ N	Y / ☐ N	Y / ☐ N	

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/28/2015

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: tracy.cole@apachecorp.com	
Date: 5-17-15	
Phone: 575-441-5196	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015

h