

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENTHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA Inc	API Number 30-025 29925 -
Property Name DRENKARD NOW MEXICO R State NCA-3	Well No. R-24 ✓

Surface Location

Comp	Sec	Range	Town	Section	East Line	East Foot	East Line	County
P	1	18S	34E	860	5	660	E	Lea

Well Status

YES	PROD WFL	YES	SHUT IN	NO	INI	INTERIOR	SWD	PRODUCER	GAS	DATE
	NO		NO					NO		5/22/15

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	ϕ	ϕ	ϕ	35	400
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	N	N	N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected f/c
Water	Y / N	Y / N	Y / N	Y / N	Water level if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Megan Phelps	Entered into RBDMS
Title: FS	Re-test
Email Address: GGLM@Chevron	
Date: 5/22/15	Phone: 505-631-8504

JUL 31 2015