

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA, Inc		Well Group 30-025-31930 -	
Property Name DRENKARD	County NEW MEXICO	State R	Well No. NG-3 R-25 -

Surface Location									
Section I	Line 1	Corner 185	Point 34E	Section 1980	US Date 5	Feet From 660	Feet To E	Feet Lea	County -

Well Status


PRODUCER YES ☒	SHUT-IN YES ☒	INJ YES ☒	INJECTOR YES ☒	SWD YES ☒	OIL YES ☒	GAS YES ☒	DATE 5/22/15
--	---	---	--	---	---	---	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	4	4	4	35	220
Flow Characteristics					
Pull	Y/N Y	Y/N Y	Y/N Y	Y/N Y	CO2 -
Steady Flow	Y/N Y	Y/N Y	Y/N Y	Y/N Y	WTR -
Surges	Y/N Y	Y/N Y	Y/N Y	Y/N Y	GAS -
Down to nothing	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Type of Fluid
Gas or Oil	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Injected for
Water	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Water level if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Megan Priepps	Entered into RBDMS
Title: FS	Re-test
E-mail Address: OG@Chevron	
Date: 5/22/15	Phone: 575-631-8504



JUL 31 2015