

JUL 27 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENTHEAD TEST REPORT

Operator Name CHEVRON USA Inc	Oil Property 30-025-31990 ✓
Property Name DRENNARD N.M. 'R' STATE ACCT. 1	Well No. R-13 ✓

Surface Location									
Section G	Range 6	Location 18S	Zone 35E	Section 1905	Well Line N	Feet from 2130	Flow Unit E	County LEA ✓	

Well Status

PROD WELL YES	NO	SHUT-IN YES	NO	INJECTOR YES	NO	PRODUCER YES	NO	DATE 5/22/15
------------------	----	----------------	----	-----------------	----	-----------------	----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	4	N/A	4 N/A	35	60
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterhead if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: MELISSA PHELPS	Entered into RBDMS
Title: FS	Re-test
E-mail Address: OG LME@Chevron	
Date: 5/22/15	575-631-8504

JUL 31 2015