

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name CHEVRON USA Inc	Oil Number 38-425-832018
Property Name DRENKARD NM R STATE #	Acct No. R-14

Surface Location

Block B	Section 6	Range 18S	Township 35E	East from 860	US Line N	Feet from 2000	Foot Line E	County LEA
-------------------	---------------------	---------------------	------------------------	-------------------------	---------------------	--------------------------	-----------------------	----------------------

Well Status

PROD WELL ☒	SHUT-IN ☒	INJ ☒	INJECTOR ☒	PRODUCER ☒	DATE 5/22/15
--	--	--	---	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	0	35	60
Flow Characteristics					
Pull	0 / N	Y / N	Y / N	Y / N	CO ₂ ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	0 / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZCL@chevron.com	
Date: 5/22/15	Phone: 505-631-8504

JUL 31 2015