

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC	Well Number 36-025-32019
Property Name DRENKARD	Well Name R-15

Surface Location

Section A	Line 6	Range 18S	Zone 35E	Section 510	Line N	Range 640	Zone E	Section LEA
---------------------	------------------	---------------------	--------------------	-----------------------	------------------	---------------------	------------------	-----------------------

Well Status


YES	PRODUCER	YES	NO	NO	INJ	SWD	OIL	GAS	DATE
									5/22/15


OBSERVED DATA

	(A)Surface	(B)Intermt(1)	(C)Intermt(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	35	120
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water level if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: MCCAY PHELPS	Entered into RBDMS
Title: FS	Re-test
E-mail Address: OGUN@Chevron	
Date: 5/22/15	Phone: 575-631-8504



JUL 31 2015

