HOBBS OCD

JUL 27 2015

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
CHEVRON USA INC	30-025-33569

Property Name	Well No.
NQOBA NEW MEXICO 'O' STATE NCT-1	O-39

Surface Location

Unit Ltr	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
G	36	17-S	34-E		2075	N	2110	E	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	INJ SWD	(OIL) GAS	5/28/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	—	—	320	35
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2 ___
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ___
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS ___
Down to nothing	(Y) / N	Y / N	Y / N	Y / (N)	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZCL@chevron.com	
Date: 5/27/15 Phone: 575-513-5526	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015