

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 27 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC		API Number 34-025-33570
Property Name NGOBA	State BA	Well No. BA-14

Surface Location

Area A	Section 36	Range 17S	Town 34E	Section 990	County N	Feet From 330	Feet From E	County LEA
------------------	----------------------	---------------------	--------------------	-----------------------	--------------------	-------------------------	-----------------------	----------------------

Well Status

PROD WELL ☒ YES	SHUT-IN ☒ NO	INJECTOR ☐ INJ	SWD ☐ SWD	PRODUCER ☒ OIL	GAS ☐ GAS	DATE 5/22/15
--	---	--	-------------------------------------	---	-------------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	35	240
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected f/c
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TECL@chevron.com	
Date: 5/22/15	Phone: 575-513-5526

JUL 31 2015