

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	CHEVRON USA Inc	Well Number	34-025-33854 ✓
Property Name	NQOBA	Well Name	Q-12 ✓
State			
NEW MEXICO			

Surface Location

Section	25	Range	17S	Zone	34E	Section	400	Zone	S	Section	1900	Zone	E	County	LEA
---------	----	-------	-----	------	-----	---------	-----	------	---	---------	------	------	---	--------	-----

Well Status

YES	PROD WELL	YES	SHUT-IN	YES	INJECTOR	YES	PRODUCER	DATE	5/22/15
YES	NO	YES	NO	YES	NO	YES	NO		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	Ø	N/A	35	50
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Water flood if
					applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BA 7/29/2015

Signature		OIL CONSERVATION DIVISION
Printed name	Ruben Rodriguez	Entered into RBDMS
Title	FSA	Re-test
E-mail Address	TRCL@chevron.com	
Date	5/22/15	55-513-5526

JUL 31 2015