

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 27 2015

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA		RECEIVED 5-30-025-34097	
Property Name ABC REEF		Well No. AN-11	
State - AN			

Surface Location

Section B	Section 7	Section 18S	Section 35E	Section 900	Section N	Section 1440	Section E	Section LEA
---------------------	---------------------	-----------------------	-----------------------	-----------------------	---------------------	------------------------	---------------------	-----------------------

Well Status

YES ☐	NO ☒	YES ☐	NO ☐	YES ☐	NO ☐	YES ☐	NO ☒	YES ☐	NO ☐	DATE 5-22-15
---------------------------------	---	---------------------------------	--------------------------------	---------------------------------	--------------------------------	---------------------------------	---	---------------------------------	--------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	50	320
Flow Characteristics					
Pull	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Water added if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TRCL@chevron	
Date: 5-22-15	Phone: 575-513-5526

JUL 31 2015