

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC	Well Number 38-025-34945
Property Name NQOBA	State BA

Surface Location

Section C	Well 34	Block 175	Foot 34E	Section W12	Well N	Foot 2135	Section W	County LEA
---------------------	-------------------	---------------------	--------------------	-----------------------	------------------	---------------------	---------------------	----------------------

Well Status

PROD WELL ☒	SHUT IN ☒	INJECTOR ☒	SWD ☒	PRODUCER ☒	GAS ☒	DATE 5/22/15
--	--	---	--	---	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm1	(C) Interm2	(D) Prod Csg	(E) Tubing
Pressure	$\varnothing$	$\varnothing$	N/A	250 40	250
Flow Characteristics					
Pull	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Water Added if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZEL@chevron.com	
Date: 5/22/15	Phone: 575-513-5526

JUL 31 2015