

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name CHEVRON USA, Inc		Well Number 30-025-41296
Property Name ABC REEF	Well Name Urate AN	Well No. AN-15

Surface Location

Grid G	Section 7	Range 18 S	Zone 35 E	Section 1070	North N	East 1450	North E	County LEA
------------------	---------------------	----------------------	---------------------	------------------------	-------------------	---------------------	-------------------	----------------------

Well Status


PROD WELL ☒	SHUT-IN ☒	INJ ☒	INJECTOR ☒	SWD ☒	PRODUCER ☒	GAS ☒	DATE 5/22/15
--	--	--	---	--	---	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	50	270
Flow Characteristics					
Pull	Y / 0	Y / N	Y / N	Y / 0	CO2 ☐
Steady Flow	Y / 0	Y / N	Y / N	Y / 0	WTR ☐
Surges	Y / 0	Y / N	Y / N	Y / 0	GAS ☐
Down to nothing	Y / 0	Y / N	Y / N	Y / 0	Type of Fluid
Gas or Oil	Y / 0	Y / N	Y / N	Y / 0	Injected for
Water	Y / 0	Y / N	Y / N	Y / 0	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/29/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZC@chevron.com	
Date: 5-22-15	Phone: 575-513-5526

JUL 31 2015

