

HOBBS OCD

JUL 10 2015

RECEIVED

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Apache Corp</i>	API Number <i>30-025-04126</i>
Property Name <i>NMGSAU</i>	Well No. <i>1315</i>

7. Surface Location									
UL - Lot <i>0</i>	Section <i>35</i>	Township <i>19S</i>	Range <i>36E</i>		Feet from <i>660</i>	N/S Line <i>5</i>	Feet from <i>1980</i>	E/W Line <i>E</i>	County <i>Lea</i>

Well Status								DATE
TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ	SWD	OIL	GAS	<i>7-7-15</i>

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	<i>0</i>		<i>0</i>	<i>80</i>	<i>695</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

JUL 31 2015

BS 7/28/2015

Signature: <i>J. Ellison</i>	OIL CONSERVATION DIVISION
Printed name: <i>Jim Ellison</i>	Entered into RBDMS
Title: <i>Instrument Tech</i>	Re-test
E-mail Address: <i>J.D. Ellison @ apache corp. com</i>	
Date:	
Phone: <i>575-441-7734</i>	
Witness:	