

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA, Inc.	API Number 30025340370000
Property Name HOOVER 27	Well No. 002

Surface Location

BL - Lot K	Section 27	Township 17 S	Range 35 E	Feet from 2145	N/S Line S	Feet from 1980	E/W Line W	County LEA
----------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE 6-3-2015
--	--	--	--	-------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	20	170
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterfall if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Tubing - 170 Continuous
Casing - 20 Continuous
Surface - Bleed down to zero
Interm - Bleed down to zero

B8 7/29/2015

Signature 	OIL CONSERVATION DIVISION
Printed name EVERARD SILAS	Entered into RBDMS
Title Field Specialist "B"	Re test
Email Address ESILAS@CHEVRON.COM	
Date 6-3-2015	Phone (505) 704-2270

JUL 31 2015

