

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	Well Number 30-025-33850 ✓
Property Name NQOBA	Well Name Q-12 ✓

Surface Location

Section 0	Section 25	Section 17S	Section 34E	Section 400	Section S	Section 1900	Section E	Section LEA
---------------------	----------------------	-----------------------	-----------------------	-----------------------	---------------------	------------------------	---------------------	-----------------------

Well Status

PROD WELL ☒	SHUT-IN ☒	INJECTOR ☒	PRODUCER ☒	DATE 5/22/15
--	--	---	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm1	(C)Interm2	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	35	50
Flow Characteristics					
Pull	Y / ☒	Y / ☒	Y / N	Y / ☒	CO2 ☐
Steady Flow	Y / ☒	Y / ☒	Y / N	Y / ☒	WTR ☐
Surges	Y / ☒	Y / ☒	Y / N	Y / ☒	GAS ☐
Down to nothing	Y / ☒	Y / ☒	Y / N	Y / ☒	Type of fluid injected for
Gas or Oil	Y / ☒	Y / ☒	Y / N	Y / ☒	Waterhead if applies
Water	Y / ☒	Y / ☒	Y / N	Y / ☒	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature 	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TRCL@chevron.com	
Date: 5/22/15	

AUG 04 2015